Affected Products

Product Series	Mercury+ KX2
Affected Product Model	All product models
Affected Parts	[EN101776] ME-KX2-160-2I-D11-P-R2 [EN101778] ME-KX2-410-2I-D11-P-R2 [EN102097] ME-KX2-410-2I-D11-P-ZB-R2
Replacement Parts	[EN105754] ME-KX2-160-2I-D11-P-R2.3 [EN105755] ME-KX2-410-2I-D11-P-R2.3 [EN105756] ME-KX2-410-2I-D11-P-ZB-R2.3

Type of PCN, Description and expected impact for customers

Type of PCN	**A – Post on Enclustra Website** ☐ Removal of Product Model (if no customer is affected) ☐ Minor Revision without impact on customer ☐ Other, specify: **B – Inform current customers** ☐ Increase of minimum order quantity (MOQ) ☐ Status Changes to end-of-life (EOL) ☐ Removal of Product Model (if customer is affected) ☐ Major Revision roll-out ☒ Minor Revision with impact for customer ☐ Other, specify: **C – Inform all affected customers** ☐ Security related bug / Major non-conformance to specification ☐ Other, specify:
Description of change	FTDI Software Change - new configuration for the FT2232H USB-to-Serial bridge
Reason for change	Enable AMD JTAG functionality
Expected impact on customer	The configuration of the FTDI device changed and now offers AMD JTAG functionality. In Vivado, the Mercury+ KX2 module is shown as Xilinx_tcf/Xilinx/EnclustraA. MCT version 2.10.1 or above allows to revert to the old software (**Device mode** set to **Standard**) or upgrade to the new software (**Device mode** set to **Xilinx JTAG**). Customer software using the FTDI device may have to change.
Forecasted key milestones	Last Time Buy (LTB) date: N/A Last Time Ship (LTS) date: N/A

Details of change

Details	Refer to "Mercury+ KX2 Known Issues and Changes" document available on Enclustra download site.

Contact

Details

If you have any questions or require additional information, please contact support@enclustra.com.
Web: www.enclustra.com