

Product Change Notification for Enclustra Mercury ZX5 Revision 3 FPGA Module

Enclustra PCN: 00005

Date: November 28, 2016

Type of change:	<ul style="list-style-type: none">▪ Change of hardware components
Description of change:	<ul style="list-style-type: none">▪ The purpose of this notice is to inform you that the revision 3 of the product uses a different EEPROM (ATSHA204) than the earlier revisions. See Known Issues and Changes for more information.
Reason for change:	<ul style="list-style-type: none">▪ EOL expected (EEPROM).▪ Harmonization of Enclustra modules
Forecasted key milestones:	<ul style="list-style-type: none">▪ none
Customer impact of change and recommended action:	<ul style="list-style-type: none">▪ Minor design changes might be necessary when migrating designs from Revision 2 or earlier. See Reference Design User manual for more information.

Products affected:	Part number	Part name
	EN100640	ME-ZX5-15-2C-D10-R1
	EN100641	ME-ZX5-15-2I-D10-R1
	EN100642	ME-ZX5-30-1C-D10-R1
	EN100643	ME-ZX5-30-1I-D10-R1
	EN100873	ME-ZX5-30-2I-D10-R1
	EN100981	ME-ZX5-15-2C-D10-R2
	EN100982	ME-ZX5-15-2I-D10-R2
	EN100983	ME-ZX5-30-1C-D10-R2
	EN100984	ME-ZX5-30-1I-D10-R2
	EN101173	ME-ZX5-30-3C-D10-R2

Replacement part numbers:	Part number	Part name
	EN101485	ME-ZX5-15-2C-D10-R3
	EN101486	ME-ZX5-15-2I-D10-R3
	EN101487	ME-ZX5-30-1C-D10-R3
	EN101488	ME-ZX5-30-1I-D10-R3
	EN101489	ME-ZX5-30-3C-D10-R3

Response:	No response is required.
------------------	--------------------------

Contact:	If you have any questions or require additional information, please contact info@enclustra.com
-----------------	--