

Product Change Notification for Enclustra Mercury+ XU8 Revision 2 SoC Module

Enclustra PCN: 00012

Date: August 2nd, 2019

Type of change:	▪ New revision rollout								
Description of change:	▪ The purpose of this notice is to inform you that a new revision of the product is planned for release in the following months. See Known Issues and Changes for more information.								
Reason for change:	▪ Manufacturing process optimization and general product improvements.								
Forecasted key milestones:	▪ New revision rollout expected Q4 2019/Q1 2020.								
Customer impact of change and recommended action:	▪ Minimal impact. See Known Issues and Changes for more information.								
Products affected:	<table border="1"> <thead> <tr> <th>Part number</th> <th>Part name</th> </tr> </thead> <tbody> <tr> <td>EN102310</td> <td>ME-XU8-4CG-1E-D11E-R1.1</td> </tr> <tr> <td>EN102311</td> <td>ME-XU8-5EV-1I-D12E-R1.1</td> </tr> <tr> <td>EN102312</td> <td>ME-XU8-7EV-2I-D12E-R1.1</td> </tr> </tbody> </table>	Part number	Part name	EN102310	ME-XU8-4CG-1E-D11E-R1.1	EN102311	ME-XU8-5EV-1I-D12E-R1.1	EN102312	ME-XU8-7EV-2I-D12E-R1.1
Part number	Part name								
EN102310	ME-XU8-4CG-1E-D11E-R1.1								
EN102311	ME-XU8-5EV-1I-D12E-R1.1								
EN102312	ME-XU8-7EV-2I-D12E-R1.1								
Replacement part numbers:	<table border="1"> <thead> <tr> <th>Part number</th> <th>Part name</th> </tr> </thead> <tbody> <tr> <td>EN102340</td> <td>ME-XU8-4CG-1E-D11E-R2</td> </tr> <tr> <td>EN102341</td> <td>ME-XU8-5EV-1I-D12E-R2</td> </tr> <tr> <td>EN102342</td> <td>ME-XU8-7EV-2I-D12E-R2</td> </tr> </tbody> </table>	Part number	Part name	EN102340	ME-XU8-4CG-1E-D11E-R2	EN102341	ME-XU8-5EV-1I-D12E-R2	EN102342	ME-XU8-7EV-2I-D12E-R2
Part number	Part name								
EN102340	ME-XU8-4CG-1E-D11E-R2								
EN102341	ME-XU8-5EV-1I-D12E-R2								
EN102342	ME-XU8-7EV-2I-D12E-R2								
Response:	No response is required.								
Contact:	If you have any questions or require additional information, please contact info@enclustra.com								