

Enclustra - Product Change Notification (PCN)

No.:	PCN_SP_2025-006
Date:	27.02.2025

Affected Products	
Product Series	Mercury+ XU9
Affected Product Model	ME-XU9-4CG-1E-D11E ME-XU9-5EV-1I-D12E-L11 ME-XU9-7EG-2E-D11E-L13 ME-XU9-7EV-2E-D13E
Affected Parts	[EN105299] ME-XU9-4CG-1E-D11E-R3.0 [EN105300] ME-XU9-5EV-1I-D12E-L11-R3.0 [EN105301] ME-XU9-7EG-2E-D11E-L13-R3.0 [EN105302] ME-XU9-7EV-2E-D13E-R3.0
Replacement Parts	[EN105303] ME-XU9-7EV-2I-D12E-L11-R3.0

Type of PCN, Description and expected impact for customers		
Type of PCN	A – Post on Enclustra Website	
	☑ Removal of Product Model (if no customer is affected)	
	☐ Minor Revision without impact on customer	
	☐ Other, specify:	
	B – Inform current customers	
	☐ Increase of minimum order quantity (MOQ)	
	☐ Status Changes to end-of-life (EOL)	
	☐ Removal of Product Model (if customer is affected)	
	☐ Major Revision roll-out	
	☐ Minor Revision with impact for customer	
	☐ Other, specify:	
	C – Inform all affected customers	
	☐ Security related bug / Major non-conformance to specification	
	☐ Other, specify:	
Description of change	Mercury ME-XU9-4CG-1E-D11E and ME-XU9-5EV-1I-D12E-L11 and ME-XU9-7EG-2E-D11E-L13	
	changed to End-of-Life and therefore are no longer available for sales	
Reason for change Obsolen	Obsolence	
	obsoletiee	
Expected impact on	No impact on the customer; a replacement part is available.	
customer	·	
Forecasted key milestones	Last Time Buy (LTB) date: N/A	
	Last Time Ship (LTS) date: N/A	

Details of change	
Details	Refer to Enclustra website or reach out to us.

Contact

Details

If you have any questions or require additional information, please contact support@enclustra.com.

Web: www.enclustra.com

Template No: ED42010-02 Page 1 of 1