

Affected Product series

Product Series	Mercury CA1
Affected Configuration	ME-CA1-30-8C-D7
Affected Parts	All parts from this configuration
Replacement Parts	N/A

Type of PCN, Description and expected impact for customers

Type of PCN	<p>A – Post on Enclustra Website</p> <p><input type="checkbox"/> Removal of Product Configuration (if no customer is affected)</p> <p><input type="checkbox"/> Minor Revision without impact on customer</p> <p><input type="checkbox"/> Other, specify:</p> <p>B – Inform current customers</p> <p><input checked="" type="checkbox"/> Increase of minimum order quantity (MOQ)</p> <p><input type="checkbox"/> Product Status Changes to end-of-life (EOL)</p> <p><input type="checkbox"/> Removal of Product Configuration (if customer is affected)</p> <p><input type="checkbox"/> Major Revision roll-out</p> <p><input type="checkbox"/> Minor Revision with impact for customer</p> <p><input type="checkbox"/> Other, specify:</p> <p>C – Inform all affected customers</p> <p><input type="checkbox"/> Security related bug / Major non-conformance to specification</p> <p><input type="checkbox"/> Other, specify:</p>
Description of change	New minimum order quantity (MOQ) for the specified product configuration: 80 units (previously MOQ=1).
Reason for change	Very low customer demand
Expected impact on customer	After stock depletion, need to order MOQ for this configuration.
Forecasted key milestones	Last Time Buy (LTB) date: 27.07.2020 (for single unit orders) Last Time Ship (LTS) date: 27.01.2021 (for single unit orders) Note: ordering and shipping may be possible after specified dates if stock is available.

Details of change

Details	None
----------------	------

Contact

Details

If you have any questions or require additional information, please contact info@enclustra.com.

Web: www.enclustra.com