

Affected Product series

Product Series	Mercury CA1
Affected Configuration	ME-CA1-115-8C-D8
Affected Parts	All parts from this configuration
Replacement Parts	All parts from the following configuration: ME-CA1-115-7I-D8

Type of PCN, Description and expected impact for customers

Type of PCN	<p>A – Post on Enclustra Website</p> <p><input type="checkbox"/> Removal of Product Configuration (if no customer is affected)</p> <p><input type="checkbox"/> Minor Revision without impact on customer</p> <p><input type="checkbox"/> Other, specify:</p> <p>B – Inform current customers</p> <p><input type="checkbox"/> Increase of minimum order quantity (MOQ)</p> <p><input type="checkbox"/> Product Status Changes to end-of-life (EOL)</p> <p><input checked="" type="checkbox"/> Removal of Product Configuration (if customer is affected)</p> <p><input type="checkbox"/> Major Revision roll-out</p> <p><input type="checkbox"/> Minor Revision with impact for customer</p> <p><input type="checkbox"/> Other, specify:</p> <p>C – Inform all affected customers</p> <p><input type="checkbox"/> Security related bug / Major non-conformance to specification</p> <p><input type="checkbox"/> Other, specify:</p>
Description of change	The specified configuration has been removed and after stock depletion this will no longer be available.
Reason for change	Very low customer demand
Expected impact on customer	After stock depletion, use replacement part for new orders.
Forecasted key milestones	<p>Last Time Buy (LTB) date: 27.07.2020</p> <p>Last Time Ship (LTS) date: 27.01.2021</p> <p>Note: ordering and shipping may be possible after specified dates if stock is available.</p>

Details of change

Details	None
----------------	------

Contact

Details

If you have any questions or require additional information, please contact info@enclustra.com.

Web: www.enclustra.com