

Enclustra - Product Change Notification (PCN)

No.:	PCN_SP_2024-004
Date:	06.05.2024

Affected Products	
Product Series	Mercury+ PE1
Affected Product Model	All product models
Affected Parts	[EN104219] ME-PE1-200-C-R4.7 [EN104220] ME-PE1-300-W-R4.7 [EN104222] ME-PE1-300-W-X1-R4.7 [EN104221] ME-PE1-400-W-R4.7
Replacement Parts	[EN105764] ME-PE1-200-C-R4.8 [EN105766] ME-PE1-300-W-R4.8 [EN105767] ME-PE1-300-W-X1-R4.8 [EN105769] ME-PE1-400-W-R4.8

Type of PCN, Description and expected impact for customers		
Type of PCN	A – Post on Enclustra Website Removal of Product Model (if no customer is affected) Minor Revision without impact on customer Other, specify: B – Inform current customers Increase of minimum order quantity (MOQ) Status Changes to end-of-life (EOL) Removal of Product Model (if customer is affected) Major Revision roll-out Minor Revision with impact for customer Other, specify: C – Inform all affected customers Security related bug / Major non-conformance to specification Other, specify:	
Description of change	FTDI Software Change - new configuration for the FT2232H USB-to-Serial bridge	
Reason for change	Enable AMD JTAG functionality	
Expected impact on customer	The configuration of the FTDI device changed and now offers AMD JTAG functionality. In Vivado, the Mercury+ PE1 base board is shown as Xilinx_tcf/Xilinx/EnclustraA. MCT version 2.10.1 or above allows to revert to the old software (Device mode set to Standard) or upgrade to the new software (Device mode set to Xilinx JTAG). Customer software using the FTDI device may have to change.	
Forecasted key milestones	Last Time Buy (LTB) date: N/A Last Time Ship (LTS) date: N/A	

Details of change	
Details	Refer to "Mercury+ PE1 Known Issues and Changes" document available on Enclustra download
	site.

Contact

Details

If you have any questions or require additional information, please contact support@enclustra.com.

Web: www.enclustra.com

Template No: ED42010-02 Page 1 of 1